



## **Bonanza Society Service Clinic**

### **Engine Discrepancies**

**N484D**

**Engine Model: IO-520-BB**

**Engine Serial: 1011903**

1. Fuel Injectors leaking
2. Hose chaffing Right Rear Intake Pipe
3. Gami tags should be removed from Fuel Lines
4. #3, #4, and #5 Push Rod Tubes leaking
5. Rocker Box Covers leaking oil
6. Exhaust Clamps installed incorrectly
7. Ignition Wires should be over the Fuel Lines
8. Zip Ties on Left Rear Intake Pipes should have Hose Clamps
9. Fuel leak @ Fuel Divider