



Bonanza Society Service Clinic

Engine Discrepancies

N567EB

Engine Model: IO-550-B

Engine Serial: 1012170

1. Gami Injector Tags should be removed from Fuel Lines
2. Tach Cable is loose
3. Zip Ties on Left Side Intake Should be removed
4. Oil Leak Left Magneto
5. Push Rod Tube Seals Leaking Oil
6. Rocker Box Covers Leaking Oil
7. Upper Through Bolt Leaking Oil