



Mailing Address:
 120 Airport Avenue West
 Venice, FL 34285 USA

 www.SarasotaAvionics.com

Pro-Forma Invoice

Quote #: Q634656
Date: 5/16/2023
Time: 3:49:55 PM
of Items: 14
Page: 1
Prepared By: HENRIQUE, EXT. 111

Toll Free: 1-888-289-0997 • Local: 1-941-360-6877 • Fax: 1-941-360-6878

To:
 ALMAN BONANZA FLYING CLUB
 MIAMI, FL
 UNITED STATES

Ship To:
 ALMAN BONANZA FLYING CLUB

Quote Date: 5/1/2023 **Ref #:** **Phone #:** +1 305 586 4547 **Fax #:**
Code: ABFC1 **Site:** **Contact:**
Terms: WIRE **Email:**

The following is in response to your Request For Quote

| Item | Part Number/Description | CD | Qty | Unit Price | Line Amt |
|------|---|----|-----|-------------|-----------|
| 1 | 930-6CP-2 EDM930 6CYL (2 TANK, CERTIFIED) Delivery Terms: STOCK | NE | 1 | 7,489.00EA | 7,489.00 |
| 2 | CC284022-DGTL FUEL LEVEL SENDER (Digital) Delivery Terms: STOCK ESTIMATE BASED ON 2 TANKS 4 SENDERS, ACTUAL FUEL TANK CONFIGURATION MAY REQUIRE ADDITIONAL SENDERS | NE | 4 | 695.00EA | 2,780.00 |
| 3 | INSTALL INSTALLATION LABOR Delivery Terms: STOCK INSTALL EDM930 AND CIES DIGITAL SENDERS | NE | 80 | 125.00EA | 10,000.00 |
| 4 | 010-02002-05 GTN750Xi SYSTEM Delivery Terms: STOCK PRICE WITH TRADE IN OF GNS530W Garmin GTN UPGRADE: 530W to GTN 750Xi GNS530W must be a multi-voltage unit with black faceplate, subject to evaluation | NE | 1 | 14,189.00EA | 14,189.00 |
| 5 | CORE CORE CHARGE CORE CHARGE REFUNDED IF THE GNS530W TRADE IN PASSES BENCH EVALUATION, IF THE TRADE IN FAILS BENCH INSPECTION THE CORE CHARGE IS NOT REFUNDED | | 1 | 2,410.00 | 2,410.00 |
| 6 | 010-02486-50 GNC255A NAV/COMM (10W) Delivery Terms: STOCK | NE | 1 | 4,589.00EA | 4,589.00 |
| 7 | INSTALL INSTALLATION LABOR Delivery Terms: STOCK | NE | 18 | 125.00EA | 2,250.00 |
| 8 | PARTS MISCELLANEOUS PARTS (AVIONICS STOC K) Delivery Terms: STOCK MISC PARTS NEEDED TO COMPLETE THE JOB SUCH AS WIRE, COAX, BNC CONNECTORS, CIRCUIT BREAKERS, ETC. WILL BE INVOICED AT THE END BASED ON WHAT IS USED. | NE | 1 | | No Quote |

Quote valid for 30 days. Any freight, sales tax and/or other misc charges will be added as required. Estimated labor/equipment may change if circumstances arise that could not be predicted prior to arrival. Not responsible for any losses/claims resulting from delays in delivery of goods or services, or for typographical or clerical errors. 20% restock fee will apply to cancellations after an order is placed. As-is and special order sales are final. Trade-ins subject to evaluation. Unless otherwise specified, removed equipment is the property of SAI. All warranty work to be performed by SAI.

Authorized Signature:



Mailing Address:
 120 Airport Avenue West
 Venice, FL 34285 USA
 www.SarasotaAvionics.com

Pro-Forma Invoice

Quote #: Q634656
Date: 5/16/2023
Time: 3:49:55 PM
of Items: 14
Page: 2
Prepared By: HENRIQUE, EXT. 111

Toll Free: 1-888-289-0997 • Local: 1-941-360-6877 • Fax: 1-941-360-6878

To:
 ALMAN BONANZA FLYING CLUB
 MIAMI, FL
 UNITED STATES

Ship To:
 ALMAN BONANZA FLYING CLUB

Quote Date: 5/1/2023 **Ref #:** **Phone #:** +1 305 586 4547 **Fax #:**
Code: ABFC1 **Site:** **Contact:**
Terms: WIRE **Email:**

The following is in response to your Request For Quote

| Item | Part Number/Description | CD | Qty | Unit Price | Line Amt |
|------|--|----|-----|------------|----------|
| 9 | NOTES NOTES CHANGES AND ADDITIONS TO SWITCHES AND CIRCUIT BREAKERS WILL BE LABELED WITH P-TOUCH LABELS AS REQUIRED | | 1 | | No Quote |
| 10 | 010-02544-21 GSB15 DUAL USB TYPE-A/TYPE-C, R EAR POWER INPUT Delivery Terms: STOCK | NE | 1 | 389.00EA | 389.00 |
| 11 | 6420093-5 CH93MAX DIGITAL CLOCK (DUAL USB-A /C, 3.0 AMPS) Delivery Terms: STOCK | NE | 1 | 699.00EA | 699.00 |
| 12 | INSTALL-LNA INSTALLATION LABOR:LANTANA Delivery Terms: STOCK | NE | 1 | 125.00EA | 125.00 |
| 13 | PANELS CUSTOM AIRCRAFT PANEL Delivery Terms: STOCK NEW FLAT PANEL WITH GLOBE BOX. | NE | 1 | 8,500.00EA | 8,500.00 |
| 14 | PANEL1 CUSTOM AIRCRAFT PANEL CIRCUIT BREAKER PANEL RELABEL AND RE LAMP AS REQUIRED CHARGES FOR INDIVIDUAL CIRCUIT BREAKERS ARE INVOICED UNDER THE MISC PARTS LINE REPLACE OLD STYLE BREAKERS WITH PULL TYPE BREAKERS AS REQUIRED | | 1 | 1,500.00 | 1,500.00 |

INSTALLATION PAYMENT SCHEDULE:
 1. 20% deposit due upon acceptance of quote.
 2. Balance of equipment due by check or wire transfer on or before the original scheduled start date.
 3. Remaining balance of equipment and labor due by check or wire transfer prior to delivery.
 Credit card payments not to exceed a total of \$5,000.00.
 Please note that initial deposits are used to secure equipment in advance of the aircraft's arrival. If install is cancelled within 30 days of scheduled arrival date the deposit will be forfeited to cover vendor restocking fees and schedule adjustment.

Quote valid for 30 days. Any freight, sales tax and/or other misc charges will be added as required. Estimated labor/equipment may change if circumstances arise that could not be predicted prior to arrival. Not responsible for any losses/claims resulting from delays in delivery of goods or services, or for typographical or clerical errors. 20% restock fee will apply to cancellations after an order is placed. As-is and special order sales are final. Trade-ins subject to evaluation. Unless otherwise specified, removed equipment is the property of SAI. All warranty work to be performed by SAI.

| | |
|---------------------|-----------|
| Sub Total: | 52,510.00 |
| Misc Charge: | 2,410.00 |
| Freight: | 0.00 |
| Total: | 54,920.00 |
| Payable in USD | |

Authorized Signature: